

Oil Field Environmental Incident Summary

Incident: 20160506154312 **Date/Time of Notice:** 05/06/2016 15:43

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: TYLER 1-19H

Field Name: UPLAND

Well File #: 21451

Date Incident: 5/6/2016

Time Incident: 10:00

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 96

Sec: 19

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	5	Gallons

Recovered	Units
-----------	-------

Followup	Units
0.12	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/17/2016

Clean Up Concluded: 5/27/2016

Risk Evaluation:

None

Areal Extent:

60x30 feet lightly misted off location

Potential Environmental Impacts:

Vegetation

Action Taken or Planned:

Well was shut in. Soil samples will be taken to determine adequate clean-up actions.

Wastes Disposal Location: TBD

Agencies Involved: Notified Johnathan Rumpee NDIC by phone on 5/6/2016 at 3:30 PM CT

Updates

Date: 5/6/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 5 gallons of oil were not contained to the well pad. More follow-up needed.

Date: 5/11/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

5/11/2016 at 14:11, on location. Walked wellpad boundary; found no evidence of staining along fenceline or on vegetation bordering fenceline. Wellpad grade slopes gently to the east into conservation (PLOTS) land, and there appears to be some slight erosion in this direction; however, no staining is visible in the erosion features.